

# Oil Field Environmental Incident Summary

**Incident:** 20160421173437      **Date/Time of Notice:** 04/21/2016 17:34

**Responsible Party:** OASIS PETROLEUM NORTH AMERICA LLC

**Well Operator:** OASIS PETROLEUM NORTH AMERICA LLC

**Well Name:** SONOMA 19-30-161-92HOR

**Field Name:** FOOTHILLS

**Well File #:** 21051

**Date Incident:** 4/20/2016

**Time Incident:** 12:04

**Facility ID Number:**

**County:** BURKE

**Twp:** 161

**Rng:** 92

**Sec:** 18

**Qtr:**

**Location Description:**

**Submitted By:** Tim Christianson

**Received By:**

**Contact Person:** Dustin Anderson  
1001 FANNIN STE 1500  
HOUSTON, TX 77002

**General Land Use:** Pasture

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Treater Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	30	Barrels	27	Barrels		

Brine

Other

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

None

**Areal Extent:**

Approximately 50 feet to the west & 400 feet to the North

**Potential Environmental Impacts:**

Low impact

**Action Taken or Planned:**

Cleaned up oil & put back into facility. Treater is shut down & we are in process of washing out for repair. Also have Calistoga treater shut down & washed out for Preventive repair.

**Wastes Disposal Location:**

**Agencies Involved:**

**Updates**

---

**Date:** 4/22/2016    **Status:** Reviewed - Follow-up Required

**Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the report, the release was not contained. Further follow-up needed.

---

**Date:** 5/3/2016    **Status:** Inspection

**Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

I arrived on location at 1800. Oil had misted off the pad near the treaters. Oil staining visible along grassland on west side of pad. Oil residue was also found off of the north side of the pad. Oil staining reached a small wetland area surrounded by birch trees. The wetland was mostly dried up, but I was able to get some water samples. I did not see any oil sheen in the water. Group 190 and diesel range organics (DRO) samples were taken, and a chloride strip test resulted in a non-detect. There is a larger pond behind this wetland, but it sustained no oil impacts. Further cleanup needed.

---

**Date:** 5/17/2016    **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on location 17:32, 5/17/2016.

Minimal impacts to areas off of location. Slight staining on trees and grasss. Company contact is going to produce a closure report.

No on-site follow-up is necessary, but will follow up with phone call.

---

**Date:** 11/2/2016    **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on location 6:04, 11/2/2016.

Slight staining on trees, but there doesn't appear to be any remaining impacts.

No follow-up is necessary.